

**From:** [Sanchez, Carlos](#)  
**To:** [Miller, Garyg](#)  
**Subject:** RE: San Jacinto Rock Placement Photos  
**Date:** Wednesday, March 16, 2016 7:20:48 AM

---

Gary,

It looks like they are carry the rock by barge and then placing it by hand.CAS

---

**From:** Miller, Garyg  
**Sent:** Wednesday, March 16, 2016 7:17 AM  
**To:** Sanchez, Carlos  
**Subject:** FW: San Jacinto Rock Placement Photos

Carlos,

Some more pics of rocking.

Gary Miller  
Remedial Project Manager  
EPA Region 6 – Superfund Division (6SF-RA)  
214-665-8318  
[miller.garyg@epa.gov](mailto:miller.garyg@epa.gov)

---

**From:** Rick Coupe [<mailto:rcoupe@anchoragea.com>]  
**Sent:** Tuesday, March 15, 2016 6:47 PM  
**To:** Miller, Garyg <[Miller.Garyg@epa.gov](mailto:Miller.Garyg@epa.gov)>  
**Cc:** Holly Samaha <[hsamaha@anchoragea.com](mailto:hsamaha@anchoragea.com)>  
**Subject:** San Jacinto Rock Placement Photos

Hi Gary,

Please see a couple of the rock placement photos from today attached.

Thanks,

**Rick Coupe**

**ANCHOR QEA, LLC**  
[rcoupe@anchoragea.com](mailto:rcoupe@anchoragea.com)  
614 Magnolia Ave.  
Ocean Springs, MS 39564  
Office – 228-818-9626 ext. 228  
Cell – 601-941-6832

**ANCHOR QEA, LLC**  
[www.anchoragea.com](http://www.anchoragea.com)

Please consider the environment before printing this email.

This electronic message transmission contains information that may be confidential and/or privileged work product prepared in anticipation of litigation. The information is intended for the use of the individual or entity named above. If you are not



9769181

the intended recipient, please be aware that any disclosure, copying distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at (206) 287-9130.